

Model Number	Vendor	Mode	SIM Card	SIM card locked?	PIN Locked?	AT+GCAP	ATI
MF190	ZTE	WCDMA	y	n	n	"GCAP: +CGSM,+DS,+ES"	"Manufacturer: ZTE COPORRATION Model: MF190 Revision: BD_MF190V1.0.0B04 IMEI: 861648009695267 +GCAP: +CGSM,+DS,+ES"
MF190	ZTE	WCDMA	n	n	n	ERROR	"Manufacturer: ZTE COPORRATION Model: MF190 Revision: BD_MF190V1.0.0B04 IMEI: 861648009695267 +GCAP: +CGSM,+DS,+ES"
MF668	ZTE	WCDMA	y	n	n	"GCAP: +CGSM,+DS,+ES"	"Manufacturer: ZTE INCORPORATED Model: MF668 Revision: BD_ROGERMF668V1.0.1B01 IMEI: 355987030038011"
MF668	ZTE	WCDMA	n	n	n	ERROR	"Manufacturer: ZTE INCORPORATED Model: MF668 Revision: BD_ROGERMF668V1.0.1B01 IMEI: 355987030038011"
E1750	Huawei	WCDMA	y	n	n	"GCAP: +CGSM,+DS,+ES"	"Manufacturer: huawei Model: E1750 Revision: 11.124.05.04.112 IMEI: 354818043490165 +GCAP: +CGSM,+DS,+ES"
E1750	Huawei	WCDMA	n	n	n	"CME ERROR: SIM failure"	"Manufacturer: huawei Model: E1750 Revision: 11.124.05.04.112 IMEI: 354818043490165 +GCAP: +CGSM,+DS,+ES"
E173	Huawei	WCDMA	y	n	n	"GCAP: +CGSM,+DS,+ES"	"Manufacturer: huawei Model: E173 Revision: 11.126.85.01.127 IMEI: 356345048363740 +GCAP: +CGSM,+DS,+ES"
E173	Huawei	WCDMA	n	n	n	"CME ERROR: SIM failure"	"Manufacturer: huawei Model: E173 Revision: 11.126.85.01.127 IMEI: 356345048363740 +GCAP: +CGSM,+DS,+ES"
E153	Huawei	WCDMA	y	n	n	"GCAP: +CGSM,+DS,+ES"	"Manufacturer: huawei Model: E153 Revision: 11.609.18.01.233 IMEI: 354429040538046 +GCAP: +CGSM,+DS,+ES"
E153	Huawei	WCDMA	n	n	n	"CME ERROR: SIM failure"	"Manufacturer: huawei Model: E153 Revision: 11.609.18.01.233 IMEI: 354429040538046 +GCAP: +CGSM,+DS,+ES"
Olive vm100	Olive	WCDMA	y	n	n	"GCAP: +CGSM,+DS,+ES"	"Manufacturer: Model: HSPA WIRELESS MODEM Revision: 3.0.1 IMEI: 910540400144840 +GCAP: +CGSM,+DS,+ES"

Olive vm100	Olive	WCDMA	n	n	n	ERROR	"Manufacturer: Model: HSPA WIRELESS MODEM Revision: 3.0.1 IMEI: 910540400144840 +GCAP: +CGSM,+DS,+ES"
u3505	i-Mobile	WCDMA	y	n	n	"+GCAP: +CGSM,+DS,+ES"	"Manufacturer: Manufacturer Model: HSPA USB MODEM Revision: LQA0083.1.2_MG32 IMEI: 352161048126225 +GCAP: +CGSM,+DS,+ES"
u3505	i-Mobile	WCDMA	n	n	n	ERROR	"Manufacturer: Manufacturer Model: HSPA USB MODEM Revision: LQA0083.1.2_MG32 IMEI: 352161048126225 +GCAP: +CGSM,+DS,+ES"
su8000	Speedup	WCDMA	y	n	n	"+GCAP: +CGSM,+DS,+ES"	"Manufacturer: Model: SU-8000 Revision: 3.0.4 IMEI: 355189031366885 +GCAP: +CGSM,+DS,+ES"
su8000	Speedup	WCDMA	n	n	n	ERROR	"Manufacturer: Model: SU-8000 Revision: 3.0.4 IMEI: 355189031366885 +GCAP: +CGSM,+DS,+ES"
su8900	Speedup	WCDMA	y	n	n	"+GCAP: +CGSM,+DS,+ES"	"Manufacturer: Manufacturer Model: HSPA USB MODEM Revision: LQA0085.1.2_M038 IMEI: 356940040331263 +GCAP: +CGSM,+DS,+ES"
su8900	Speedup	WCDMA	n	n	n	ERROR	"Manufacturer: Manufacturer Model: HSPA USB MODEM Revision: LQA0085.1.2_M038 IMEI: 356940040331263 +GCAP: +CGSM,+DS,+ES"
su9800	Speedup	WCDMA	y	n	n	"+GCAP: +CGSM,+DS,+ES"	"Manufacturer: Manufacturer Model: HSPA USB MODEM Revision: LWA6R04.1.0_MG35 IMEI: 355132040089759 +GCAP: +CGSM,+DS,+ES"
su9800	Speedup	WCDMA	n	n	n	ERROR	"Manufacturer: Manufacturer Model: HSPA USB MODEM Revision: LWA6R04.1.0_MG35 IMEI: 355132040089759 +GCAP: +CGSM,+DS,+ES"
su8650	Speedup	WCDMA	y	n	n	"+GCAP: +CGSM,+DS,+ES"	"Manufacturer: Manufacturer Model: HSPA USB MODEM Revision: LQA6R15.1.0_MG32 IMEI: 352161049351012 +GCAP: +CGSM,+DS,+ES"
su8650	Speedup	WCDMA	n	n	n	ERROR	"Manufacturer: Manufacturer Model: HSPA USB MODEM Revision: LQA6R15.1.0_MG32 IMEI: 352161049351012 +GCAP: +CGSM,+DS,+ES"

EC1261	Huawei	CDMA2000	y	n	n	"+GCAP: +CIS707-A,CIS-856-A,+MS, +ES, +DS, +FCLASS"	"Manufacturer: +GMI: HUAWEI TECHNOLOGIES CO., LTD Model: EC1261 Revision: +CGMR:11.102.11.00.45 ESN: +GSN:80c2f550 +GCAP: +GCAP: +CIS707-A,CIS-856-A,+MS, +ES, +DS, +FCLASS"
EC1261	Huawei	CDMA2000	n	n	n	"+GCAP: +CIS707-A,CIS-856-A,+MS, +ES, +DS, +FCLASS"	"Manufacturer: +GMI: HUAWEI TECHNOLOGIES CO., LTD Model: EC1261 Revision: +CGMR:11.102.11.00.45 ESN: +GSN:09450148 +GCAP: +GCAP: +CIS707-A,CIS-856-A,+MS, +ES, +DS, +FCLASS"
EC1261	Huawei	CDMA2000	y	n	y	"+GCAP: +CIS707-A,CIS-856-A,+MS, +ES, +DS, +FCLASS"	"Manufacturer: +GMI: HUAWEI TECHNOLOGIES CO., LTD Model: EC1261 Revision: +CGMR:11.102.11.00.45 ESN: +GSN:00000000 +GCAP: +GCAP: +CIS707-A,CIS-856-A,+MS, +ES, +DS, +FCLASS"
olive vm-e101	Olive	CDMA2000	n (ROM)	y	n	"+GCAP: +CIS707-A, CIS-856, +MS, +ES, +DS, +FCLASS"	"Manufacturer: EVDO Datacard Model: CE210TATA Revision: OLME101DT02 ESN: 80630655 +GCAP: +CIS707-A, CIS-856, +MS, +ES, +DS, +FCLASS"
AG2726	ZTE	CDMA2000	y	n	n	"+GCAP: +CIS707-A, CIS-856, +MS, +ES, +DS, +FCLASS"	"Manufacturer: ZTEMT INCORPORATED Model: 119 Revision: +CGMR:AC8710_V3_LU9A7732_CTAT ESN: 0x80C55FAF +GCAP: +CIS707-A, CIS-856, +MS,
AG2726	ZTE	CDMA2000	y	n	y	"+GCAP: +CIS707-A, CIS-856, +MS, +ES, +DS, +FCLASS"	"Manufacturer: ZTEMT INCORPORATED Model: 119 Revision: +CGMR:AC8710_V3_LU9A7732_CTAT ESN: 0x34F5C67 +GCAP: +CIS707-A, CIS-856, +MS,
AG2726	ZTE	CDMA2000	n	n	n	"+GCAP: +CIS707-A, CIS-856, +MS, +ES, +DS, +FCLASS"	"Manufacturer: ZTEMT INCORPORATED Model: 119 Revision: +CGMR:AC8710_V3_LU9A7732_CTAT ESN: 0x80F6E923 +GCAP: +CIS707-A, CIS-856, +MS,
EC156	Huawei	CDMA2000	n (ROM)	y	n	"+GCAP: +CIS707-A,CIS-856-A,+MS, +ES, +DS, +FCLASS"	"Manufacturer: +GMI: HUAWEI TECHNOLOGIES CO., LTD Model: EC167 Revision: 11.104.04.00.224 ESN: +GSN:00000000 +GCAP: +CIS707-A,CIS-856-A,+MS, +ES, +DS, +FCLASS"

EC150	Huawei	CDMA2000	n (ROM)	y	n	"+GCAP: +CIS707-A,CIS-856-A,+MS, +ES, +DS, +FCLASS"	"Manufacturer: +GMI: HUAWEI TECHNOLOGIES CO., LTD Model: EC150 Revision: 11.104.04.00.224 ESN: +GSN:00000000 +GCAP: +CIS707-A,CIS-856-A,+MS, +ES, +DS, +FCLASS"
-------	--------	----------	---------	---	---	---	---